

Regd. No. : 11317021

COSMOPOLIS RESIDENTS WELFARE ASSOCIATION

At / Po : Dumduma, P.S. Khandagiri, Bhubaneswar - 751019, Khurda, Odisha
E-mail : cosmopollsrwa@gmail.com

Ref. No. 29/2019-20.....

Date 3/10/19.....

NOTICE

In order to assess the extent of damage to the outer wall and repairing of the same, all flat owners/residents are requested to report the details of damages like cracks in the wall, seepage etc of the outer wall to maintenance office by 10th October 2019. They are also requested to mark the seepage area to facilitate the repairing outside as it will be difficult to locate once the rain stops & dry season sets in.

Thanks

R.K. - 1/1
3/10/2019

General Secretary

(C.R.W.A)